

2013 Honda Fit 1.3 13G S Package		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GK3	DISPLACEMENT 1,317 cc		
YEAR / REG. 2013/10	MILEAGE 44,526 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. GK3-3002251	DIMENSIONS (L X W X H) 395 × 169 × 152 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Door mirror scratches, minor exterior scratches and dents, underbody rust, front bumper lower scratches, faint exterior line scratches, console scratches, interior dirt. Front windshield has scratches, stone chips, cracks, and repair marks, requiring major repair or replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年10月		車名・グレード フィット 13G・Sパッケージ		2WD 4WD		評価点 (4.5)	
ディーラー・並行 型式 DBA-GK3		排気量 1300		ドア 5		定員 5人	
モデル年式 年 ハンドル 左・右		形状 CC		積載 kg		外装 内装 B B	
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限ります)			
車検 年 月 (日)		冷暖房 AAC		スマートキー・ETC			
走行 4万4千526 km		燃料 ガソリン		Bluetooth・フルセグ・TV・バックカメラ			
色 シルバー		色コード NH823M/6F4		諸備品 (純正品に限り○をつけてください)			
R券 9,880 円				(PS) (PW) (ABS) (エアB) (AW) SR ナビ TV カワ			
注意事項申告欄				新車保証書 有・無			
ドアミラー キズ							
外装 小A・小U							
下廻り サビ							
Ftバンパー下キズ							
外装 うすい傷キズ							
コンソール キズ							
室内 汚れ							
フロントガラス 内装		(キズ・傷) ヒビ割・リペア跡・X要 (キズ・傷) コゲ・穴・スレ・キレ・破れ		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済 型式指定番号 17566 識別区分番号 0006 車検有効期 395 長さ 169 高さ 152			
車台番号 3002251							
登録番号							