


2021 Mazda Carol 5D GL		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2021/08	MILEAGE 89,238 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. HB36S-602613	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Core support D, Bumper reinforcement D, Side member D			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 8月		メーカー マツダ 車名 キャロル		ドア枚数 5	ボディ構造 軽四	評価点 R																				
グレード GL		駆動方式 2WD		4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 5BA-HB36S	通称 型式	内装 A・B・C																						
車検 - - 年 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																							
走行 口内にマークを記入 (金・交換・点検・点検)	シフト AT																									
外装色 ホワイト	カラーNo. ()	エアコン ()	新着品のみ O印 を記入																							
内装色 ()	標準定員 人	サンルーフ 車シート																								
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料 8,420円	預託金	エブリック																				
セールスポイント		 修復歴 ○ 無																								
検査記入欄		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ/ヘコミ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
書類送付は成約後10日前後がかかります。		登録No. 月 日 までに名義できる方																								
コアサポートD		名義中																								
バンパーホースメントD		月 日 までに名義できる方																								
サイドメンバーD		HB36S-602613																								
FW (トビ)	シミ	ヤブレ	コガ	コガ穴	オーディ穴	シリアル No.																				
内装 (ヨコ)	シミ	ヤブレ	コガ	コガ穴	オーディ穴	車検 cm																				
最大積載量 kg		cm																								