

2015 MITSUBISHI Outlander PHEV G Premium Package		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DLA-GG2W	1,998 cc		
YEAR / REG.	MILEAGE		
2015/09	64,070 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GG2W-0304131	466 × 180 × 168 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats (Leather)		Power Tailgate	
Pre-Collision Braking		Adaptive Cruise Control	
Side Camera		Back Camera	
Front Camera		Navigation System	
Rockford Fosgate Premium Sound Syst...			
INSPECTOR REPORT			
Core support XX and distortion, right front side member tip distortion, charging cable missing, repaired.			

初年度登録	三菱	5	SUV/クロカン	年式別
H27/9月	車名 アウトランダーPHEV	グレード Gプレミアムパッケージ	車検 2WD	3
車種 自動車・その他	排気量 2000	形式 CC	型式 DLA-GG2W	所属 A・B・C
車検 - 年 - 月 - 日	燃料 ガソリン	ディーゼル ハイブリッド	後日送付品（保証書・取扱説明書等）	
走行 （走行キロメートル（表）・交換（※）（※）（※）（※）（※））	シフト フロア	AT		
外装色 パール（W13）	カラーメ AD・WD・WAC・（）	エンジン AG・WD・WAC・（）	新車品のみ O印を記入	
（）	内装色 （）	乗車定員 5人	（P）	（Q）
左・右・後 左・右・後	ディーゼル・走行	11,100円	（R）	（S）
セールスポイント		全方位モニター、スマートキー、LEDヘッドライト、LDW、レーダークルーズコントロール、革革シート、AC100V、パワーバックドア		
検査記入欄				
コアシポートXX・ヒズミ、右フサイドメンバ先ヒズミ、充電ケーブル欠、補修		修復歴 有、 ⑤ A キズ U ヘッドランプ B キズ・ヘッド C 色あせ・サビ D 錆 E 交換 F 交換 G 交換 H 交換 I 交換 J 交換 K 交換 L 交換 M 交換 N 交換 O 交換 P 交換 Q 交換 R 交換 S 交換 T 交換 U 交換 V 交換 W 交換 X 交換 Y 交換 Z 交換 登録地 月 日 家でに名でできる 車体番号 GG2W-0304131 年式 2WD 車種 SUV 形式 DLA-GG2W 燃料 ガソリン 車検 2WD 所属 A・B・C		