2003 Suzuki Alto Lapin X2

OVERALL	EXTERIOR	INTERIOR
3.5	-	-

MODEL CODE HE21S	DISPLACEMENT 658 cc
YEAR / REG. 2003/12	MILEAGE 72,790 km
DOORS 5	SEATS 4
TRANSMISSION AT	FUEL Petrol
STEERING Right	EXTERIOR COLOR Pink
BODY TYPE Kei	
CHASSIS NO. HE21S-435105	DIMENSIONS (L X W X H) 340 × 148 × 152 cm

SALES POINTS

Alloy Wheels

Navigation System

INSPECTOR REPORT

Some paint peeling, including on the side mirrors. Exterior has noticeable scratches and dents. Interior has some noticeable stains. No abnormalities in the structural parts.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H15/12月 | メーカー スズキ | ドア枚数 5 | ボディ形状 軽四 | 評価点 3.5
車名 アルトラパン | グレード X 2
車歴 自家用 | 車検 8年12月/抹消 | 型式 HE21S | 排気量 660 | 燃料 ガソリン | 内装 B
走行 □内にマークを記入（§：実績 ＊：改ざん #：不明） 7,790 マイル | 駆動 | エアコン AC | 乗車定員 Kg
外装色 ピンク | カラーNo. ( ) | リサイクル料 9,080円・預託証 | 車台番号 HE21S-435105
( ) 塗装車は（）内に「色番」を記入 | 内装色 | シフト コラム 4 AT | 乗車定員 4 人 | 長さ cm | 幅 cm | 高さ cm
持込り品 (保証書 ・ 取扱説明書 等)
装備 ABS ナビ TV
セールスポイント
査定員記入欄
塗装一部剥げあり・サイドミラー色剥げ
※ダメージレベルに関する注意事項
クオリティグレード説明
外装:気になるようなキズやヘコミがあります。
内装:気になる汚れ等が、部分的にあります。
修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート C68220J2301
鑑定日 2020年10月23日 | 再鑑定日
クオリティーグレード | 外装 ★★★ | 内装 ★★★★ | 修復歴 無 | 機関 正常
車両状態の説明
極小 500円玉程度未満 | 小 カードサイズ程度未満 | 中 A4サイズ程度未満
大 A4サイズは上 | 箇所 5～6箇 | 箇所 7箇以上
本コンディションチェックシートは鑑定時点の車両状態を示し、評価については他検査機関等の評価と異なる場合があります。