2005 Honda Integra 3HB Type S

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE DC5	DISPLACEMENT 1,998 cc
YEAR / REG. 2005/11	MILEAGE 37,202 km
DOORS 3	SEATS 4
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Orange	BODY TYPE Coupe
CHASSIS NO. DC5-2304435	DIMENSIONS (L X W X H) 439 × 173 × 140 cm

SALES POINTS

Alloy Wheels

Sunroof

INSPECTOR REPORT

Exterior: Noticeable scratches and dents have been repaired, but small scratches and dents remain. Interior: Some noticeable stains are present. Repair history: No abnormalities in the structural components.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H17/11月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 4
	車名 インテグラ	グレード タイプS		
車庫 自家用	輸入区分	ハンドル 右	型式 DC5	排気量 2000
燃料 ガソリン	内装 B	車検 - - 年 月 / 未	走行 37,202 マイル	駆動
エアコン AC	積載量 Kg	外装色 オレンジ	カラーNo. ( )	リサイクル料 11,650円
車台番号 DC5-2304435	(色替)	内装色	シフト フロア 5 AT	乗車定員 4 人
長さ cm	幅 cm	高さ cm		

後日送り品 (保証書 ・ 取扱説明書 等)

装備: ABS エアバック ナビ TV キーレス

セールスポイント: ABS/助手席エアバック

査定員記入欄

※ダメージレベルに関する注意事項

クオリティグレード説明

外装:気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。

内装:気になる汚れ等が、部分的にあります。

修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート D24126F1501

鑑定日	2026年6月15日	再鑑定日			
クオリティーグレード	外装	★★★★	内装	★★★★	修復歴 修復歴 無

車両状態の説明

小	カードサイズ未満	中	A4サイズ未満	大	A4サイズ以上	数個	2個以上

タイヤ残溝は実測の程度を目視により判定しています。(より厳密ではありません)
(例:残 5分山 = 概ね5ミリ=センチ程度残溝量を示す)

<対応車項>
外装 鈑金塗装(色替え含む) 凹みあり
外装 錆あり

<ウィンドウ類の状態>
フロントウインドウ 飛び石傷 部分的

<灯火類(ライト等の状態)>
右ヘッドライト 曇り・くすみ 部分的
左ヘッドライト 曇り・くすみ 部分的

<内装特記事項>
シート/ダッシュ 汚れ、きず
太陽モ しみ・汚れ 部分的
他パネル しわ・すれ・きず 部分的

車両状態の確認は、停止状態で実施できる範囲で行っています。