2010 BMW_Mini BMW Mini 3HB 50 Camden

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE SU16	DISPLACEMENT 1,598 cc
YEAR / REG. 2010/08	MILEAGE 89,750 km
DOORS 3	SEATS 4
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Black	BODY TYPE Hatchback
CHASSIS NO. WMWSU32040TY89120	DIMENSIONS (L X W X H) 370 × 169 × 143 cm

SALES POINTS

Alloy Wheels

Leather Seats (Cloth & Leather)

harman/kardon HiFi Loudspeaker System

INSPECTOR REPORT

Exterior: Worrisome scratches and dents have been repaired, but small scratches and dents remain.
Interior: Worrisome stains, etc., are partially present. Repair history: No abnormalities in the frame components.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H22/8月	メーカー MINI	ドア枚数 3	ボディ形状 コンパクト/ハッチバック	評価点 4
	車名 MINI	グレード 50 カムデン		
車検 自家用	ディーラー	右	型式 SU16	総気筒 1600
燃料 ガソリン	内装 B	車検 - - 年 月	走行 89,750 km	駆動
ミッション AC	乗車定員	外装色 ブラック	カラーNo.	リサイクル料 16,090円
車台番号 WMWSU32040TY89120	シフト フロア 6 AT	乗車定員 4 人	長さ cm	幅 cm
高さ cm	後日送り品 保証書・取扱説明書 等	装備	セールスポイント	CD/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック
査定員記入欄	※ダメージレベルに関する注意事項	クオリティグレード説明	外装:気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。	内装:気になる汚れ等が、部分的にあります。
修復歴:骨格部位に異常はありません。				

グー鑑定 コンディションチェックシート

鑑定日	2021年9月22日	再鑑定日	
クオリティーグレード	外装 ★★★★	内装 ★★★★	修復歴 無

車両状態の説明

極小	500円玉程度未満	小	カードサイズ程度未満	中	A4サイズ程度未満
大	A4サイズ以上	傷個	5~6個	箇所	7個以上

本コンディションチェックシートは鑑定時点の車両状態を示し、評価については他検査機関等の評価と異なる場合があります。