2010 BMW_Mini BMW Mini Convertible Cooper Convertible

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE MR16	DISPLACEMENT 1,598 cc
YEAR / REG. 2010/08	MILEAGE 58,100 km
DOORS 2	SEATS 4
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Red	BODY TYPE Convertible
CHASSIS NO. WMWMR32070TL36424	DIMENSIONS (L X W X H) 370 × 169 × 142 cm

SALES POINTS

Alloy Wheels

INSPECTOR REPORT

Exterior: Minor scratches and dents have been repaired, but small scratches and dents remain. Interior: There are some noticeable stains, but only in parts. Repair history: No abnormalities in the frame.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H22/8月	メーカー MINI	ドア枚数 2	ボディ形状 オープン（カブリオレ・コンバーチブル）	評価点 4
	車名 MINI	グレード クーパー コンバーチブル		
車庫 自家用	輸入区分 ディーラー	ハンドル 右	型式 MR16	排気量 1600
燃料 ガソリン	内装 B			
車検 9年8月／抹消	走行 58,100 マイル	駆動	エンジン AC	積載量 Kg
外装色 ブルー	カラーNo. ( )	リサイクル料 16,840円・預託無	車台番号 WMWMR32070TL36424	
( )	内装色	シフト フロア 6 AT	乗車定員 4 人	長さ cm 幅 cm 高さ cm

後日送り品 (保証書 ・ 取扱説明書 等)

装備: ABS エアバッグ ナビ TV

セールスポイント: CD/運転席エアバック/盗難防止システム/キーレスエントリー/ＡＢＳ/助手席エアバック/サイドエアバック

査定員記入欄

※ダメージレベルに関する注意事項

クオリティグレード説明

外装:気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。

内装:気になる汚れ等が、部分的にあります。

修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート R30426D0709

鑑定日	2026年4月7日	再鑑定日	
クオリティーグレード	外装 ★★★★	内装 ★★★★	修復歴 修復歴 無
機関 正常			

車両状態の説明

小	カードサイズ未満	中	A4サイズ未満	大	A4サイズ以上	数個	2個以上

車両状態の確認は、停止状態で実施できる範囲で行っています。