2014 Nissan Elgrand Rider

OVERALL	
4	
EXTERIOR	INTERIOR
-	-

MODEL CODE DBA-TE52	**DISPLACEMENT** 2,488 cc
YEAR / REG. 2014/04	**MILEAGE** 64,700 km
DOORS 5	**DRIVETRAIN** 2WD (FF)
TRANSMISSION AT	**FUEL** Petrol
STEERING Right	**EXTERIOR COLOR** Black
BODY TYPE Minivan	
CHASSIS NO. TE52-075377	**DIMENSIONS (L X W X H)** 498 × 185 × 181 cm

SALES POINTS

Alloy Wheels
Front Camera
Leather Seats
Navigation System

INSPECTOR REPORT

Rear panel dent, studless tires, aftermarket suspension (unconfirmed), worn steering wheel, headliner stains, uneven exterior repair.

ORIGINAL JAPANESE AUCTION SHEET



初年度登録 H26 4月 | メーカー 日産 | ドア枚数 5 | ボディ形状 ミニバン/ワンボックス | 評価点 4
車名 エルグランド | グレード ライダー | 駆動区分 2WD / 4WD
車歴 自家用 | 排気量 2500 cc | 型式 DBA-TE52 | 車検 9年4月 抹消 | 燃料 ガソリン / ディーゼル / ハイブリッド | 内装 A・B・C
走行 64,700 マイル | シフト AT | 外装色 ブラック | カラーNo. GAE | エアコン AC・ACC・WAC | 乗車定員 | 内装色
ハンドル 左・右 | 輸入区分 ディーラー・並行 | リサイクル料 15,740円 | 装備品のみ ○印 を記入: PS PW AW サンルーフ 革シート エアバック ABS ナビ TV キーレス

セールスポイント
メーカーナビ、フルセグTV、アラウンドビューモニター、両側パワースライドドア、純正フリップダウンモニター、黒ハーフレザーシート

検査記入欄
Rパネルヘコミ、スタッドレスT、外品足廻り？、ハンドルハゲ、天張シミ、外装補修ムラ

修復歴 有・(無)

A キズ	U ヘコミ・ナサレ	B キズ・ヘコミ	P 色あせ・ボケ	G ガラスキズ
W 補修跡	S サビ	C 腐食	X 交換有	XX 交換済

登録No. | 名変中 | 月 日 までに名変できる方
車体番号 TE52-075377
シリアルNo.
車輌 長さ cm 幅 cm 高さ cm 最大積載量 Kg