2015 SUBARU XV 2.0i-L EyeSight

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE GP7	DISPLACEMENT 1,995 cc
YEAR / REG. 2015/11	MILEAGE 60,974 km
DOORS 5	SEATS 5
DRIVETRAIN 4WD	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Pearl White	BODY TYPE SUV
CHASSIS NO. GP7-110310	DIMENSIONS (L X W X H) 445 × 178 × 160 cm

SALES POINTS

Alloy Wheels
Adaptive Cruise Control
Cruise Control
Navigation System

INSPECTOR REPORT

Exterior: Notable scratches and dents have been repaired, but small scratches and dents remain.
Interior: There are some noticeable stains, partially. Repair history: No abnormalities in the frame components.

ORIGINAL JAPANESE AUCTION SHEET


青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録	メーカー	ドア枚数	ボディ形状	評価点
H27/11月	スバル	5	SUV/クロカン	4
車名	XV	グレード	2.0i-L アイサイト	

車検	自家用	乗り方		ハンドル	右	型式	GP7	総気筒	2000	燃料	ガソリン
車検	-- 年 月 / 検	走行	60,974 マイル	駆動	4WD	ミッション	AC	乗車定員	Kg		
外装色	クリスタルホワイトパール	カラーNo.	リサイクル料	12,030円	車台番号	GP7-110310					
シフト	フロア AT	乗車定員	5 人	長さ	cm	幅	cm	高さ	cm		

後日送り品 (保証書 ・ 取扱説明書 等)

装備

セールスポイント

パワーシート/CD/バックカメラ/ETC/横滑り防止装置(ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/フルセグTV/衝突安全ボディ/4WD/アイドリングストップ/オートクルーズコントロール/DVD再生

査定員記入欄

※ダメージレベルに関する注意事項

クオリティグレード説明

外装:気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
内装:気になる汚れ等が、部分的にあります。
修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート

鑑定日	2026年7月1日	再鑑定日	
クオリティーグレード	外装 ★★★★	内装 ★★★★	修復歴 無 / 修復歴 有 / 補整 正常

車両状態の説明

小	カードサイズ未満	中	A4サイズ未満	大	A4サイズ以上	数個	2個以上

<MB記号説>
外装 錆ミず
ホイール・ヒビ・割れ 部分的
有ミクーラず

<ウィンドウ類の状態>
フロントウィンドウ 飛び石傷 部分的

<内装特記事項>
シート/ア すれ・さず
ゆるりんしわ・すれ・さず 部分的

車両状態の確認は、停止状態で実施できる範囲で行っています。