# 2016 BMW_Mini BMW Mini Clubman Cooper D Clubman

| OVERALL | EXTERIOR | INTERIOR |
|---|---|---|
| 4 | - | - |

| | |
|---|---|
| MODEL CODE<br>LDA-LR20 | DISPLACEMENT<br>1,995 cc |
| YEAR / REG.<br>2016/08 | MILEAGE<br>111,099 km |
| DOORS<br>5 | SEATS<br>5 |
| DRIVETRAIN<br>2WD (FF) | TRANSMISSION<br>AT |
| FUEL<br>Diesel | STEERING<br>Right |
| EXTERIOR COLOR<br>Gray | BODY TYPE<br>Hatchback |
| CHASSIS NO.<br>WMWLR920X02E72831 | DIMENSIONS (L X W X H)<br>427 × 180 × 147 cm |

## SALES POINTS

**Alloy Wheels**

**Back Camera**

**Navigation System**

## INSPECTOR REPORT

Steering wheel wear, headliner stains, brake warning light illuminated, roof paint stains/fading, headlights yellowing, surface cracks, interior scratches.

ORIGINAL JAPANESE AUCTION SHEET



初年度登録 H28 8月
メーカー MINI
ドア枚数 5
ボディ形状 コンパクト/ハッチバック
評価点 4
車名 MINI
グレード クーパー D クラブマン 純正ナビ Bluetooth バックカメラ ドラ
駆動区分 2WD 4WD
車歴 自家用 ・その他（ ）
排気量 2000 cc
型式 LDA-LR20
通称型式
内装 A・B・C
車検 - - 年 月 / 未満
燃料 ガソリン ディーゼル ハイブリッド（ ）
検日渡り品（ 保証書 ・ 取扱説明書 等 ）
走行 1,109,099 マイル km
シフト フロア 8 AT
スペアキー
外装色 グレー
カラーNo. B71
エアコン AC・AAC・WAC・（ ）
装備品のみ ○印 を記入
内装色
乗車定員 5 人
PS PW AW サンルーフ 革シート
ハンドル 左・右
輸入区分 デイーラー・並行
リサイクル料 19,440円 ・ 預託無
エアバック ABS ナビ TV キーレス
セールスポイント
検査記入欄
ハンドルスレ、天張シミ、ブレーキ警告灯点灯、ルーフPシミ・アセ、Hライト黄ばみ・表面ヒビ、内装キズ
修復歴 有・無
A キズ U ヘコミ・オサレ B キズ・ヘコミ P 色あせ・ボケ G ガラスキズ
W 補修跡 S サビ C 腐食 X 交換歴 XX 交換所
登録No. 名変中
月 日 までに名変できる方
車体番号 WMWLR920X02E72831
FW トビ石 傷 ワレ 外装 小 ホイル エアロ
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ
シリアルNo.
車輌 長さ cm 幅 cm 高さ cm 最大積載量 Kg