2021 Suzuki Alto 5D L

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE 5BA-HA36S	DISPLACEMENT 658 cc
YEAR / REG. 2021/09	MILEAGE 32,202 km
DOORS 5	SEATS 4
TRANSMISSION AT	FUEL Petrol
STEERING Right	EXTERIOR COLOR White
BODY TYPE Kei	
CHASSIS NO. HA36S-626122	DIMENSIONS (L X W X H) 340 × 148 × 148 cm

INSPECTOR REPORT

Signboard marks, minor damage on door mirror, seat stains and scuffs, headliner stains, hand grip scuffs, floor carpet stains and T-shaped tear.

ORIGINAL JAPANESE AUCTION SHEET



初年度登録 R3 / 9月
メーカー スズキ
ドア枚数 5
ボディ形状 軽四
評価点 4
車名 アルト
グレード L
駆動区分 2WD 4WD
車歴 自家用 ・ その他 ( )
排気量 650 cc
型式 5BA-HA36S
通称型式
内装 A ・ B ・ C
車検 - - 年 月 / 未満
燃料 ガソリン ディーゼル ハイブリッド ( )
後日送り品 (免許書 ・ 取扱説明書 等)
走行 3 2 , 2 0 2 マイル km
シフト AT
外装色 ホワイト カラーNo. (26U)
エアコン AC ・ AAC ・ WAC ・ ( )
装備品のみ ○印 を記入
( ) 色変更は( )内に「色変」と記入
内装色
乗車定員 4 人
PS PW AW サンルーフ 革シート
ハンドル 左 ・ 右
輸入区分 ディーラー ・ 並行
リサイクル料 6,960円 ・ 預託無
エアバック ABS ナビ TV キーレス

セールスポイント

ESC、ISS、AEB、デュアルセンサーブレーキサポート、車線逸脱警報、アイドリングストップ、D席シートヒーター

修復歴
有 ・ 無

A	キズ	U	ヘコミ・オサレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換要	XX	交換済

検査記入欄

カンバンアト、Dミラー A、シート汚れスレ、天張りヨゴレ、ハンドルグリップスレ、フロアーカーペットヨゴレ T ヤブレ

FW	トビ有	傷	ワレ	外装	小 A ・ U	ホイル A ・ 曲	エアロ A ・ ワレ	シリアル No.	
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	車輌	長さ cm 幅 cm 高さ cm 最大積載量 Kg

登録No.	名変中
	月 日 までに名変できる方
車体番号	HA36S-626122