2024 VOLVO VOLVOV60CrossCountry Cross Country Ultimate B5 AWD

OVERALL	EXTERIOR	INTERIOR
5	-	-

MODEL CODE 5AA-ZB420TM2	DISPLACEMENT 1,968 cc
YEAR / REG. 2024/05	MILEAGE 8,400 km
DOORS 5	SEATS 5
DRIVETRAIN 4WD	TRANSMISSION AT
FUEL Hybrid (Petrol)	STEERING Right
EXTERIOR COLOR Gray	BODY TYPE Station Wagon
CHASSIS NO. YV1ZZL1M2R2133791	DIMENSIONS (L X W X H) 479 × 190 × 151 cm

SALES POINTS

- Alloy Wheels
- Leather Seats (Perforated Fine Nappa L...
- Power Seats (Front)
- Adaptive Cruise Control
- Side Camera
- Navigation System
- Roof Rails
- Power Tailgate
- Pre-Collision Braking
- Front Camera
- Back Camera
- harman/kardon Premium Sound Audio ...

INSPECTOR REPORT

Exterior: Noticeable scratches and dents have been neatly repaired, though minor ones may still be present. Interior: Some noticeable stains are present in parts. Repair History: No abnormalities in the structural components.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R6 / 5月	メーカー ボルボ	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 5
	車名 V60	グレード クロスカントリー アルティメット B5 AWD		

車検	自家用	検査区分	ディーラー	ハンドル	右	型式	5AA-ZB420TM2	排気量	2000	燃料	ハイブリッド
内装	A	車検	9年 5月 抹消	走行	(□内にマークを記入(各：交換 ★：直ぐ ＃：不明)) 8,400 マイル km	駆動	4WD	エアコン	AC	乗車定員	Kg
外装色	グレー	カラーNo.	( )	リサイクル料	21,540円・預託無	車台番号	YV1ZZL1M2R2133791				
( )	色等単は()内に「色番」を記入	内装色		シフト	フロア 8 AT	乗車定員	5 人	長さ	cm	幅	cm 高さ cm

後日送り品 (保証書 ・ 取扱説明書 等)

装備

ABS	SRS	ASV	サンルーフ	ナビ
エアバッグ	ABS	ETC	TV	キセノン

セールスポイント

査定員記入欄

※ダメージレベルに関する注意事項

傷小は記号のみ
小は1
中は2
大は3

例
きず 傷小 ⇒ A
へこみ 小 ⇒ U1
きず 中 ⇒ A2
きず へこみ 大 ⇒ AU3

FW	トビ石	傷A	フレ	外装	小 A・U	ホイル A・B	エアロ A・フレ
内装	ヨゴレ	シミ	ヤブレ	コゲ	コウケン	オーディオ	メレ

クオリティグレード説明

外装:気になるようなキズやヘコミがあった場合は綺麗に補修済みですが、小さなキズやヘコミが残っている場合もあります。

内装:気になる汚れ等が、部分的にあります。

修復歴:骨格部位に異常はありません。

車両状態の確認は、停止状態で実施できる範囲で行っています。

グー鑑定 コンディションチェックシート K32325J0603

鑑定日	2025年10月6日		再鑑定日				
クオリティーグレード	外装	★★★★★	内装	★★★★	修復歴	修復歴 無	種類 正常

車両状態の説明

小	カードサイズ未満	中	A4サイズ未満	大	A4サイズ以上	数量	2個以上

ライヤ痕は経年の使用と目視により判定しています。(ヒリ表示ではありません)
【例：目 9分山＝概ね80パーセント程度残り溝を示す】

右 9分山	前 5分山	左 9分山	後 5分山

ベクトンクラ部の位置に/フロントクラッチ 部位不明 部位外

エッジきず 部位外	
右 9分山	左 9分山

すれ・きず 部位外

しわ・すれ 中

しわ・すれ 小

車両状態の確認は、停止状態で実施できる範囲で行っています。