

2021 Toyota Harrier S		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MXUA80	1,986 cc		
YEAR / REG.	MILEAGE		
2021/07	38,617 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MXUA80-0051961	474 × 186 × 166 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small scratches and dents remain. Interior: There are some noticeable stains in certain areas. Accident History: No abnormalities in the frame.			

新年度登録		メーカー		トヨタ		ドア数		5		新グレード		SUUV/クロカン		評価点	
R3 / 7月		車名		ハリアー		グレード		S		2000		車種		ガソリン	
		型式		MXUAB80		年式		2000				車種		ガソリン	
車種		自家用		右		左		MXUAB80		年式		2000		車種	
年式		- 年		月		日		3月 8日		16日		車種		AC	
外装色		ブラック		カラーNo.		リサイクル料		10,510円		車検番号		MXUAB8-0051961		車検料	
()		車検料 (円) 内税		シフト		フロア		AT		乗車定員		6人		車検料	
旅行取送り		(保証書・取扱説明書等)		車検料		車検料		車検料		車検料		車検料		車検料	

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント

クーラー/ナビ/バックカメラ/ETC

セルスポイント

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント

クーラー/ナビ/バックカメラ/ETC

セルスポイント

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント

クーラー/ナビ/バックカメラ/ETC

セルスポイント

バックカメラETC故障防止対策 (E S)

2/2000年6月19日

セルスポイント