

1999 Mitsubishi Pajero 5D Long Exceed

OVERALL

3.5

EXTERIOR

-

INTERIOR

-

MODEL CODE

V78W

DISPLACEMENT

3,200 cc

YEAR / REG.

1999/08

MILEAGE

100,900 km

DOORS

5

SEATS

7

DRIVETRAIN

4WD

TRANSMISSION

AT

FUEL

Diesel

STEERING

Right

EXTERIOR COLOR

White

BODY TYPE

SUV

CHASSIS NO.

V78W-0000298

DIMENSIONS (L X W X H)

474 × 188 × 186 cm

SALES POINTS

Alloy Wheels

Navigation System

INSPECTOR REPORT

Steering wheel scuffed, headliner scuffed and dirty. Minor scuffs, rust, and many scratches are present. The 4WD lamp is not illuminating. There is paint fade on the bonnet underside and paint rust on the undercarriage. All four tires (front and rear) are worn (double P) and cracked. A snorkel is installed, but the rear wiper is missing, the rear garnish paint is damaged, and the rear gate inner trim cover is missing.

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初度登録年月	車名	ドア 形状	グレード	評価点			
	11年8月	パジェロ	5W	ロングエクシード4WD	3.5			
車検	年 月 日	スロア	AD	LEDライト				
走行	100900	コラム		外品エアブリ	B			
外装色	白II	ダッシュ		外品足廻り				
内装色		AAC		カーナビモニター	B			
新車保証書	取扱説明書	ガソリン		メモリアースト				
注意事項	後日品	年・不明	D車・並	右H・左H				
検査員記入	ガラス	④-X	④-X	④-X				
	ハンドスレ、天窓リズレ							
	右前窓、ステアリング							
	4WDランプ点灯せず							
	右前・右後P7C、下回りP5							
	右後・左後P7C、下回りP5							
	フロントバンパー、R7C、R7C、R7C、R7C							
	長さ	cm	幅	cm	高さ	cm	重量	kg

