

1999 Mitsubishi Pajero 5D Long Exceed		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE V78W	DISPLACEMENT 3,200 cc		
YEAR / REG. 1999/09	MILEAGE 94,670 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. V78W-0000303	DIMENSIONS (L X W X H) 474 × 188 × 186 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Glass A X needs repair. Seat D has a hole, dirt, and tear. Steering wheel is worn, stereo hole present. Headliner is dirty, with slight headrest wear. Exterior oil A, oil seepage. Step has rust A and a dent. Minor scratches on exterior plastic parts. Large hole/damage on underbody.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初年度登録年月	車名	ドア	形状	グレード	評価点	
	H 11年9月	パジェロ	5W	ロング	ディーゼルトンボ パジェロエクシード4WD	3	
車検	2000年9月23日	型式	KH-V78W	排気量	3200cc	7人	
走行	94670	MTのみ記入	AT	セパレートギア	16バルブ	外装	
外装色	白II	内装色	白II	カラー	コンピハンドル	C	
外装色内装色	白II	カラー	白II	カラー	コンピハンドル	B	
新車保証書	取扱説明書	R券	¥15,950	名変期限	月 日迄	純正品のみ丸印	
注意	後日品	不具合箇所等					
事項	タイヤ本ダンロップグランドレーフス8分山						
検査員記入	ガラスA X要ス	内	シ	穴	破れ		
	ハンドル、ステアリング						
	天板リフト、3rdギアロック						
	外装A、オイルビツ						
	ステップ踏台A部						
	外装PVCビ						
	下足ステップ						
長さ	cm	幅	cm	高さ	cm	重量	kg

