

1999 MITSUBISHI Pajero Io 5D ZR 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE H76W	DISPLACEMENT 1,834 cc		
YEAR / REG. 1999/07	MILEAGE 123,220 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. H76W-0041845	DIMENSIONS (L X W X H) 398 × 168 × 171 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Glass needs replacement. Seat A has burn marks, holes, fuzz, and tears. Steering wheel has scuffs and dirt. Seat has sagging and tears. 4WD selector noted. Left front inner axle shaft has 2 rust spots. Undercarriage has rust, and extensive rust inside fenders. There is an oil leak.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録年月		車名		ドア	形状	グレード	評価点
11年7月		パジェロイオ		5W	ZR	4WD	3.5
型式		GF-H76W		排気量		1800cc	正員
車検		年 月 日		フロア	AT	セルシオライト	
走行		123220		コラム	MTの油	[外装] B	
外装色		パール		ダッシュ	速	[内装] B	
外装色		パール		AC	ガソリン	純正品のみ	
外装色		パール		ガソリン	軽油	丸印	
新車保証書		取扱説明書		R券	¥12180	名実期限	
注意		不具合箇所等		H76W-0041845		月 日迄	
事項		ガラス欠					
検査員記入		ガラス欠		X要ス		コゲ穴	
n:1026		系統75h					
シ:177		76h		4WDの故障			
t:10AS		27.162T					
F:107SC		2.1076		色黒			
オイル		6L					
長さ	幅	高さ	重量				
cm	cm	cm	kg				