


1999 Suzuki AltoWorks 660 RS/Z 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GF-HA22S	DISPLACEMENT 658 cc		
YEAR / REG. 1999	MILEAGE 200,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. HA22S-1006759	DIMENSIONS (L X W X H) 340 × 148 × 146 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Right baffle XX, right front inner panel BP distorted, left and right front inner panel corroded. Wheel scratches (post-repair), interior dirty, seat sagging, underbody rust. Rear wiper missing. Multiple small dents and scratches on body, general dents present.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H11/一月	メーカー スズキ	ドア枚数 3	ボディ形状 コンパクトハッチバック	評価点 R
車名 アルトワークス	グレード 660 RS/Z 4WD マニョ	駆動区分 2WD	4WD	
車種 自家用・その他()	排気量 660 cc	型式 GF-HA22S	塗装 A・B・C	
車検 -年-月-日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 20000km	マイル フロア 5 MT	シフト		
外装色 ブラックII	カラーNo. AAG・WAG・()	エアコン	装備品のみ O印 を記入	
内装色 ()	定員 4人	サンルーフ	革シート	
ベンチ 左・右	ディーラー 走行	8,430円	エレクトロニクス	ナビ TV キーレス
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/4WD				
				
検査記入欄 右バツフルXX右フィンパネBPヒズミ左右フィンパネ腐食 修理アト外ホイールキズルーム内汚れシートヘタリ下廻りサビRワイパー欠ボディ小凹(多) 小キズ有へこみ有				
名義中 月 日 までに名義できる方				
車体番号 HA22S-1006759				
シリアルNo.				
重量 cm cm cm 最大積重量 Kg				