

1999 Suzuki AltoWorks RS/Z		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
GF-HA22S	658 cc		
YEAR / REG.	MILEAGE		
1999/08	53,600 km		
DOORS	SEATS		
3	4		
TRANSMISSION	FUEL		
MT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Other		
BODY TYPE			
Other			
CHASSIS NO.	DIMENSIONS (L X W X H)		
HA22S-107717	339 × 147 × 145 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Exterior minor scratches and dents, wheel scratches, full repaint (same color) with some waviness, rear panel distortion.			

出 品 票		販売店番号 09190		保証店番号 0184		シリアル番号		評価点	
前年度登録		車 名		ドア数		グレード		駆動	
H 11 年		7姉ワクス		3		RS/Z		5TC 4WD	
8 月		型式 GF-HA22S		前年価		660 CC		燃料 ガソリン 軽油	
車検		年 月 車重		※未記入は標準		シフト		5MT 冷房 AC	
走行距離		5 万 3 千 6 0 0 km		マイル		○をつける (交換) (改ざん) (不明)		純正ナビ ○をつける 純正ナビ SR	
外装色		元色 シルバ - 色無		カラーNo.		内装色		TV録画 (社外品含む) ○をつける フルセグ ワンセグ アナログ	
車台No.		HA22S-107717		リサイクル 標記		8,430円税別		ナビ録画 (社外品含む) ○をつける HDD DVD SD	
登録No.				元金		339 円		DVD再生 CD	
定員		() 人 積載量		kg		147 cm		後付後添品 ○をつける 延長保証書 車検取説	
輸入車のメーカー		モデル		輸入形式		輸入元		ディーラー	
セルスポイント		販売店		ディーラー		銀行		ハンドル	

注意事項・不具合箇所

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

外装 小A・小U

ホイール キズ

同色全面の為

Rパネル塗り

トリアシラー

トリアシラー	キズ	ヒビ	ワレ
工機	無	ジャッキ	無