


1999 Suzuki Every Van Join Turbo VW Bus Specification		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GD-DA52V	DISPLACEMENT 657 cc		
YEAR / REG. 1999	MILEAGE 101,172 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Kei		
CHASSIS NO. DA52V-130748	DIMENSIONS (L X W X H) 340 × 148 × 187 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Exterior has scratches, dents, paint peeling/fading, and cracks. Interior has scuffs, dirt, stains, scratches, and damaged panel paint. Automatic power window and front speaker are faulty. Audio touch response is poor. Rear gate and left sliding door close poorly. There is oil seepage. The left fender is lifted, and both fender gaps are misaligned. Turn signals, hazards, position lights, and the rear room light are inoperable.			

ORIGINAL JAPANESE AUCTION SHEET

H11 / 一月		メーカー スズキ		ドア枚数 5		ボディ形状 軽四		評価点 3.5	
車名 エブリイ		グレード ジョインターボ		駆動方式 2WD		燃費区分 4WD			
車種 自家用 ・ その他 ()		排気量 660 cc		型式 GD-DA52V		登録区分 A・B・C			
年 9 年 7 月 / 扶養 無		燃料 ディーゼル		後付選用品 (保証書 ・ 取扱説明書 等)					
走行 101,172 km		シフト フロア		AT					
外装色 ブルー		カラーNo. ()		エアコン (Q) ・ AAG ・ WAG ・ ()		新選用品のみ O印 を記入			
()		内装色		乗車定員 4 人		AW		サンルーフ	
左 ・ ()		ディーラー ・ 直付		7,810円		エアバック		ABS ナビ TV キーレス	
セールスポイント									
★ワゴン仕様！アルミホイール！ETC！シートカバー！オルタネーター交換済み！									
									
修復歴 有 ・ ()									
検査記入欄									
外装キズ凹みPハガアセウキフレ、内装スレ汚れシミキズ、オート									
PW不良、フロントスピーカー不良、オーディオタッチ反応不調、									
リアゲート開まり悪い、オイル漏れ、左フェンダーウキ、左右									
フェンダーチリズレ、内装パネル塗装、左スライドドア開まり									
悪い、ウィンカー、ハザード、スモール、リアルームライト不灯									
DA52V-130748									
PW () 車A フレ 内装 () 小 () ホイール () エアロ () シアトル									
内装 () 座席 () ヤトレ コガ コガス オーディオ () 音調 () 最高速度									