

1999 Toyota Hiace Wagon Super Custom		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KZH100G	DISPLACEMENT 2,982 cc		
YEAR / REG. 1999/07	MILEAGE 160,370 km		
DOORS 4	SEATS 8		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. KZH100-0039848	DIMENSIONS (L X W X H) 469 × 169 × 195 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Steering wheel wear, minor interior wear, missing stereo, headliner stains, minor exterior wheel wear, interior trim tears, uneven paint (W-grade) on entire body due to color change, right rear instrument panel and end panel distortion.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H11/7月	メーカー トヨタ	ドア枚数 4	ボディ形状 ミニバンワンボックス	評価点 R
車名 ハイエースワゴン	グレード スーパーカスタム	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 3000 cc	型式 KZH100G	連検 型式	内装 A・B・C
車検 -年-月-日	燃料 ガソリン ハイブリッド	変速機 マニュアル オート	後日添付品(保証書・取扱説明書等)	
走行 160,370 km	マイル フロア	AT		
外装色 ブラック	カラーNo. AG・AAG・AG・	エアコン	装飾品のみ O印 を記入	
()	内装色 黒革定員	B人	CD	サンルーフ
ベンチ 左・右	輸入 区分	ディーラー	走行 14,930 km	エレクトリック ナビ
セールスポイント 外品15アルミ、タイベル交換済み(ステッカー)、Wエアバック、ABS		修復歴 0・無		
検査記入欄 ハンドルスレ、室内A、ステレオ欠穴、天張りしみ、外ホイールA、内張り破れ、色替えの為全面Wムラ、右Rインパネ・エンドパネル歪み		A キズ U へこみ サビ C 腐食 X 交換 XX 交換 ガラス G 交換		
売却日 月 日		名義中		
車体番号 KZH100-0039848				
FW シボ	フレ シボ	外装 小 大	ホイール A・曲 A・フレ	エアロ シリアル No.
内装 シボ	フロア シボ	シート シボ	オーディオ シボ	重量 kg