

2000 MITSUBISHI Pajero 5D Long Exceed 4WD D-TB		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE V78W	DISPLACEMENT 3,200 cc		
YEAR / REG. 2000/02	MILEAGE 58,580 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE SUV		
CHASSIS NO. V78W0006769	DIMENSIONS (L X W X H) 474 × 188 × 186 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Glass (A) needs replacement/repair. Seat (A) has burn marks, holes, and tears. Steering wheel is worn, interior trim has scratches/holes. Outer wheels (A) have minor scratches, studless tires. Fuel tank is dented, front right headrest is missing. Front area has extremely large scratches (SC), AU. Front/engine room has large scratches (SC), cargo area (A) has minor scratches. Camping kit is missing, oil seepage.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初度登録年月	車名	ドア	形状	グレード	評価点	
	12年2月	パジェロ	5	ドア	パジェロエクシード4WD	R	
車検	年	月	日	フロア	AT		
走行	58580	km		コラム			
外装色	シルバー	色別車は色別と記入		ダッシュ			
内装色				MTのみ記入			
新車保証書	取扱説明書	R券 ¥15,850	名変期限	月	日迄		
注意	後日品		車検				
事項	不具合箇所等		車検				
検査員記入	ガラス	④ X要ス	④ コゲ・穴	④ 汚損・破れ			
11/10/11/12	内装	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
外装	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
燃料タンク	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
Fuel SC	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
Engine SC	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
Camping kit	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ	④ 汚損・破れ			
長さ	cm	幅	cm	高さ	cm	重量	kg