

2000 MITSUBISHI Pajero 5D Long Exceed-II 4WD D-TB		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE V78W	DISPLACEMENT 3,200 cc		
YEAR / REG. 2000/10	MILEAGE 113,410 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE SUV		
CHASSIS NO. V78W-0100286	DIMENSIONS (L X W X H) 474 × 188 × 186 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Glass requires repair. Seat has burn marks, holes, sweat stains, and tears. Steering wheel shows peeling and wet stains. Power mirror base has an A-level scratch. Exterior P77 has thin paint (A-level). Outer wheels have multiple A-level scratches, dirt, and corrosion. Front bumper has scratches and repair marks. Headrests have scratches. Oil seepage is present. Front area has paint scratches (P SCR). Rear wiper is missing.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録年月 車名		ドア 形状 グレード		評価点
12年10月 パジェロ		5WロングエクシードII 4wd		3
車検 車庫番 () 型式 KH-V78W		排気量 3200cc 7人		
車検 48年11月19日		フロア AT		
走行 113410 km		MTのみ 速		
外装色 シルバー-II		内装色		
外装色 No. A69A-1		車・不明 D車・並 右・左H		
新車保証書 取扱説明書 R券 ¥15,850		名変期限 月 日迄		
注意 後日品【		車検 V78W-0100286		
不具合箇所等				
ETC、防犯モーターライト				
タイヤ4本、フロントリフト				
検査員記入 ガラス ④ X要ス ⑤ コゲ・穴・汚・破れ				
ヘッドランプ 未張り付け				
電動ミラー 不良 A、車外ミラー 不良				
外装P77、117、118				
外装117A、118A、119A、120A				
フロントバンパー補修跡、ヘッドレスト1個欠				
オイルパン、フロントP.S.C.R、R711-2				
長さ	幅	高さ	重量	kg

小A 小B 小C 小D 小E 小F 小G 小H 小I 小J 小K 小L 小M 小N 小O 小P 小Q 小R 小S 小T 小U 小V 小W 小X 小Y 小Z