


2000 Toyota Crown Majesta 3.0 A Type		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE JZS177	DISPLACEMENT 2,997 cc		
YEAR / REG. 2000/03	MILEAGE 129,400 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. JZS177-0007428	DIMENSIONS (L X W X H) 490 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Seats (Front) Crown Super Live Sound System (7 Spe...	
INSPECTOR REPORT			
Multi-display malfunction, A/C not operable, dashboard lifting, water inside marker light, S-tire house (A, U damage), interior seat (A damage).			

ORIGINAL JAPANESE AUCTION SHEET

H12/3月		メーカー トヨタ		ドア数 4	ボディ形状 セダン	評価点 4																				
クラウンマジェスタ		グレード 3.0 Aタイプ		駆動方式 2WD	4WD																					
車種 乗用車・その他 ()	排気量 3000 cc	型式 JZS177	通称 3.0	内装 A・B・C																						
年 月 日	燃料 軽油	ディーゼル	登録番号 (保証書・取扱説明書 等)																							
走行 129,400 km	シフト フロア	AT																								
外装色 ブラックII (202)	カラーNo. AG・AG・WAG ()	エアコン	装備品のみ O印 を記入																							
5人	乗車定員	5人	サンルーフ	天シート																						
14,240円	リサイクル料	14,240円	ナビ	TV																						
セールスポイント																										
純正キセノンライト、クルーズコントロール、キーレスエントリ、Wエアバッグ、Sエアバッグ、ABS、コンピシフトノブ、タイヤ交換済、キーレス、スペアキー			修復歴 有・無																							
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/凹み</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>燃費</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/凹み	B	キズ/へこみ	P	色あせ/ボケ	Q	ガラスキズ	W	燃費	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/凹み	B	キズ/へこみ	P	色あせ/ボケ	Q	ガラスキズ																	
W	燃費	S	サビ	C	腐食	X	交換済	XX	交換済																	
マルチ不良、A/C操作出来ず、ダッシュウキ、マーカー内水、SタイヤハウスA・U、室内シートA			名義中																							
			月 日 までに名義できる方																							
			JZS177-0007428																							
FR	2WD	AT	軽油	5人	14,240円	最大積載量 147kg																				