

2000 Toyota LandCruiser Prado 5D 2.7TX Limited		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GF-RZJ95W	DISPLACEMENT 2,693 cc		
YEAR / REG. 2000	MILEAGE 132,800 km		
DOORS 5	DRIVETRAIN 4WD		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Purple		
BODY TYPE SUV			
CHASSIS NO. RZJ95-0036271	DIMENSIONS (L X W X H) 469 × 173 × 208 cm		
SALES POINTS			
Alloy Wheels Navigation System		Roof Rails	
INSPECTOR REPORT			
Full repaint with partial color unevenness and paint deterioration. Hood and grille have partial paint peeling, and the left front bumper has scuffs. The roof rack is rusty. The driver's side power window is inoperable. The original seat condition is unknown.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H12 / 一月	メーカー トヨタ	ドア数 5	ボディ形状 SUV/クロカン	評価点 3
車名 ランドクルーザープラド	グレード 2.7TXリミテッド	駆動方式 4WD	燃費区分 2WD 4WD	
車種 自家用・その他 ()	排気量 2690 cc	型式 GF-RZJ95W	通称 A・B・C	内装 A・B・C
車検 132800 km	燃料 ハイブリッド ()	ディーゼル	後日送り品 (保証書・取扱説明書等)	
走行 132800 km	オイル AT	エアコン	PS	PW
所装色 マカボニー(グロスベント)	カラーNo. QD・AAG・WAG ()	エアコン	AW	サンルーフ
内装色 ()	車検定員 人	PS	PW	AW
走行 132800 km	ディーラー 11,450円	エアバック	ABS	TV
セールスポイント	A1 A2 G B			
検査記入欄	修復歴 有 (B)			
全塗装車、部分的に色ムラや塗装劣化 ボンネット・グリル一部塗装ハガ、左フロントバンパー擦り傷 ルーフラックサビ 運転席パワーウィンドウ不動 純シートコンディション不明	A 欠点 B 欠点 C 欠点 D 欠点 E 欠点 F 欠点 G 欠点 H 欠点 I 欠点 J 欠点 K 欠点 L 欠点 M 欠点 N 欠点 O 欠点 P 欠点 Q 欠点 R 欠点 S 欠点 T 欠点 U 欠点 V 欠点 W 欠点 X 欠点 Y 欠点 Z 欠点			
	名実中			
	月 日 まで名実中の方			
	RZJ 95-0036271			
	長さ 469 cm 幅 173 cm 高さ 208 cm 最大積重量 kg			