

2001 Daihatsu Mira 5D 660 CD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE TA-L700S	DISPLACEMENT 659 cc		
YEAR / REG. 2001/12	MILEAGE 47,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. L700S-0271688	DIMENSIONS (L X W X H) 340 × 148 × 143 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Minor damage to left front inner panel. Exterior faded with scratches and dents. Left and right headlights are hazy. Driver's seat and trunk have wrinkles, scuffs, and dirt.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H13/12月	メーカー ダイハツ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5
車名 ミラ	グレード 660 CD 5速MTリアスモーク 貼車高欄外12AW外シフトノ ブETC	駆動方式 4WD	4WD	
車種 自家用・その他 ()	排気量 660	型式 TA-L700S	内装 A・B・C	
車検 8年12月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 47,000 km	シフト フロア 5 MT			
外装色 シルバーメタリック	カラーNo. ()	エアコン	装備品のみ O印 を記入	
()	内装色 ()	4人	サンルーフ	革シート
ハンド 左・右	輸入 ディーラー・並行	リサイクル料 8,670円・預託料	エアバック	ABS
セールスポイント				
キーレスエントリー/運転席エアバック/助手席エアバック/メモリーナビ他/フルセグTV/ETC/ローダウン/DVD再生/ミュージックサーバー/D定期点検記録簿				
検査記入欄				
左フロントインサイドパネル経損 外装色褪せ、傷凹み 左右ヘッドライトくすみ 運転席、トランクシワ擦れ汚れ				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ W 補修跡 S サイズ C 腐食 X 交換車 XX 交換車				
登録No. 月 日 まで(名義できる方)				
車体番号 L700S-0271688				
FW トビキ 傷A フレ 外装 小 ホイール エアロ				
内装 ヨグレ シス ヤブレ コガ コガ穴 オーディオ穴				
車重 長さ 幅 高さ 最大積載量				