

|                                                                                                                                                                                  |                                              |          |          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------|----------|
| 2001 Daihatsu Move CL                                                                                                                                                            |                                              | OVERALL  |          |
|                                                                                                                                                                                  |                                              | 3.5      |          |
|                                                                                                                                                                                  |                                              | EXTERIOR | INTERIOR |
|                                                                                                                                                                                  |                                              | -        | -        |
| MODEL CODE<br>L900S                                                                                                                                                              | DISPLACEMENT<br>659 cc                       |          |          |
| YEAR / REG.<br>2001                                                                                                                                                              | MILEAGE<br>32,000 km                         |          |          |
| DOORS<br>5                                                                                                                                                                       | SEATS<br>4                                   |          |          |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                           | TRANSMISSION<br>MT                           |          |          |
| FUEL<br>Petrol                                                                                                                                                                   | STEERING<br>Right                            |          |          |
| EXTERIOR COLOR<br>Silver                                                                                                                                                         | BODY TYPE<br>Kei                             |          |          |
| CHASSIS NO.<br>L900S-0202591                                                                                                                                                     | DIMENSIONS (L X W X H)<br>340 × 148 × 163 cm |          |          |
| INSPECTOR REPORT                                                                                                                                                                 |                                              |          |          |
| Glass (X) needs repair/replacement. Interior (X) has burns, holes, stains, and tears. Oil cover (A), Battery (A), Underbody wet, Floor support distorted, Front side member (U). |                                              |          |          |

|         |  |          |  |     |  |    |  |      |  |     |  |
|---------|--|----------|--|-----|--|----|--|------|--|-----|--|
| 初年度登録年月 |  | 車名       |  | ドア  |  | 形  |  | グレード |  | 新車点 |  |
| 13 年 月  |  | ム-9"     |  | 5 W |  | CL |  |      |  | 3.5 |  |
| 車種      |  | 型式       |  | 排気量 |  | CC |  | 乗員   |  | 4 人 |  |
| 乗用車     |  | GH-L900S |  | 660 |  | CC |  |      |  |     |  |

  

|               |  |  |           |  |  |       |  |  |       |  |  |             |  |  |
|---------------|--|--|-----------|--|--|-------|--|--|-------|--|--|-------------|--|--|
| 車検            |  |  | 年 月 日     |  |  | スア AT |  |  | セ     |  |  | 外装          |  |  |
| 走行            |  |  | 3 / 6 5 0 |  |  | コラム   |  |  | MT 5  |  |  | B           |  |  |
| 外装色           |  |  | シルバー      |  |  | ダッシュ  |  |  | 5     |  |  | 内装          |  |  |
| 内装色           |  |  | シルバー      |  |  | AC    |  |  |       |  |  | B           |  |  |
| 新車保証書         |  |  | 取扱説明書     |  |  | R券 ¥  |  |  | 9,100 |  |  | 純正品のみ<br>丸印 |  |  |
| 後日品!          |  |  | 不具合箇所等    |  |  | D車・並  |  |  | 右H・左H |  |  | 名義期限        |  |  |
| L900S-0202591 |  |  |           |  |  |       |  |  |       |  |  | 月 日迄        |  |  |

  

|          |  |            |  |            |  |            |  |
|----------|--|------------|--|------------|--|------------|--|
| 検査員記入    |  | ガラス        |  | X要ス        |  | コグ・穴・透れ・破れ |  |
| ボイルカバー A |  | コグ・穴・透れ・破れ |  | Fサイドアンバー U |  |            |  |