

2001 MITSUBISHI Galant Sedan 2.5 VR-4 Type V 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GF-EC5A	DISPLACEMENT 2,498 cc		
YEAR / REG. 2001	MILEAGE 144,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Purple	BODY TYPE Sedan		
CHASSIS NO. EC5A-0500267	DIMENSIONS (L X W X H) 468 × 174 × 142 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
AC faulty, interior dirty and torn, steering wheel worn, mirror scratches, minor undercarriage damage (S-grade), minor scratches and dents, paint peeling and fading (P-grade), seat wear, scratches on right front instrument panel, bumper bent, rear spoiler bent with a hole, U-shaped core support repaired/replaced, front support repaired/replaced, floor member bent.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H13/	メーカー 三菱	ドア数 4	ボディ形状 セダン	評価点 R
車名 ギャラン	グレード 2.5 VR-4タイプ 4WD 5速 マニュアル タイミングベ ルト交換済み	駆動区分 2WD		
車種 自家用・その他 ()	排気量 2500 cc	型式 GF-EC5A	通称 A・B・C	
車検 - - - 年 / 月 / 日	燃料 ガソリン	ディーゼル ハイブリッド ()	後部選り品 (保証書・取扱説明書 等)	
走行 144,000 km	シフト フロア 5 MT	新車のみ O印 を記入		
外装色 パープル	カラーNo. QD・AAG・WAG・ ()	5人		
内装色 ()	標準定員 5人	新車のみ O印 を記入		
左・右 左・右	ディーラー 12,570円	オプション エアロック・ABS・ナビ・TV・キース		
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エ アバック/4WD				
修復歴 0. 無				
検査記入欄				
AC不良 ルーム内汚れキレ ハンドルすれ有 ミラーキズ下廻 り S 小キズ有へこみ有 ハガ Pアセ有 AC不良小キズ有 へこみ有 ハガ Pアセ有 シートへたり スレ右フインパネ BP曲がり Rスボイラー曲がりコアサポートXX f サポートXXフ ロアメンバー曲がり Rスボイラー穴				
A キズ U ヘッドランプ B キズヘッド C キズヘッド D 色あせ・ボケ E ガラスキズ W 破損部 S サビ C 腐食 X 交換済 XX 交換済				
登録月 日 まで(に名実である方)				
車検 EC5A-0500267				
シリアル No.				
長さ 幅 高さ 最大積載量 cm cm cm Kg				