


2001 MITSUBISHI Pajero lo 5D 2.0 ZR 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GH-H77W	DISPLACEMENT 1,999 cc		
YEAR / REG. 2001/02	MILEAGE 49,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE SUV		
CHASSIS NO. H77W-5201994	DIMENSIONS (L X W X H) 398 × 168 × 171 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Steering wheel scuffs, seat sagging, interior cleaned, seat edge wear, left center pillar bodywork/paint, mirror scratches, fading, right step issue, minor undercarriage rust.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H13/2月	メーカー 三菱	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 R
車名 パジェロイオ	グレード 2.0 ZR 4WD 5速 ミッション 4WD車	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 cc	型式 GH-H77W	通称 型式	内装 A・B
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検閲項目 (保証書・取扱説明書 等)	
走行 49,000 km	シフト フロア 5 MT			
外装色 ブルー	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 5 人	サンルーフ	革シート
左・右 左・右	ディーラー・並行	12,330円・預託金	ナビ	TV
セールスポイント A B S /運転席エアバック/助手席エアバック/4WD				
検査記入欄 ハンドルすれ シートへたり ルーム内洗 シートヘリ 左センターピラー BP ミラーキズ アセ 右ステップ X X 下廻りサビS		修復歴 0 . 無		
		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換済 XX 交換済		
登録No. H77W-5201994		名義中 月 日 まで(に名義できる方)		
車体番号 H77W-5201994				
FW トピ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	シリアル No.			
内装 ヨゴレ シス ヤブレ コゲ コゲ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 Kg