

2001 Nissan Cima 450XV		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
TA-GF50	4,494 cc		
YEAR / REG.	MILEAGE		
2001/04	27,781 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Gold	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GF50-009171	500 × 185 × 149 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats		Power Seats (Front)	
Cruise Control		Back Camera	
Navigation System		Cima Holographic Sound System I	
INSPECTOR REPORT			
AC not working, navigation screen burn-in, missing map disc, navigation monitor scratches, headliner sagging, dashboard cracked, steering wheel partially worn, trunk spoiler peeling, minor front wiper wear.			

初年度登録 H13 / 4月	メーカー 日産	ドア数 4	ボディ形状 セダン	評価点 4					
車名 シーマ	グレード 450XV	駆動方式 2WD 4WD							
車種 自家用・その他 ()	排気量 3500	型式 CC TA-GF50	運転形式	内装 A・B・C					
車検 - 年 月 日	燃料 ガソリン	チャイセル ハイブリッド ()	後付番号 (保証書・取扱説明書 等)						
走行 27,781 km	AT								
外装色 ゴールド (KX6)	カラーメ AG・GAG・WAG・()	新車のみ O印 を記入							
シフト 左・右・直入 5人	ボディスタイル セダン	15,180円・ 保証期間 エアロック ABS TV キーレス							
セルポイント									
本革シート、純正サランフール、バルカンキセノンヘッドライト、パワーシート、DOPサランフールバイザー、DOPフロントスポイラー、DOPドアエッジモール、DOPフェンダーアーチモール									
検査記入欄									
AC不良、ナビ画面焼け、地図ディスク欠、ナビモニターキズ、天窓ウキ、ダッシュ板ヒビ割、ハンドル部ハガ、トランクスポイラーハガ、フワイバーA									
修復歴 有 ()									
AW	キズ	U	ヘコみ等ヤケ	B	キズヘコみ	P	乗車感・ゼンケン	G	ガラスキズ
W	補修跡	S	サビ	C	変質	X	交換	XX	交換済
登録年月	月		日		家でどこに名義できるか				
車体番号	GF50-009171								
内装	シート	ヤブ	コグ	コグ	オードイ	オードイ	オードイ	オードイ	オードイ