

2001 SUBARU Pleo 660 Nesta G Special Mild Charge		OVERALL	
		4	
MODEL CODE TA-RA1		DISPLACEMENT 658 cc	
YEAR / REG. 2001/09		MILEAGE 43,000 km	
DOORS 5		SEATS 4	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Red		BODY TYPE Hatchback	
CHASSIS NO. RA1-241164		DIMENSIONS (L X W X H) 340 × 148 × 158 cm	
INSPECTOR REPORT			
Engine oil leak, minor exterior scratches, interior dirt and scratches, seat dirt, wheel cover damaged/missing, studless tires.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H13/9月		メーカー スバル		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 4	
車名 プレオ・ネスタ		グレード 660 ネスタ Gスペシャル マイ ルドチャージキーレス CD エアコン パワステ PW		駆動区分 2WD 4WD					
車歴 自家用・その他 ()		排気量 660 CC		型式 TA-RA1		通称 型式		内装 A・B・C	
車検 - 年 - 月 / 日		燃料 ガソリン		ディーゼル		ハイブリッド ()		後日送り品 (保証書・取扱説明書等)	
走行 43,000 km		シフト コラム CVT							
外装色 メローレッド・メタリック ()		カラーNo. ()		エアコン A・B・AAG・WAG・()		新備品のみ O印 を記入			
()		色車検はO印に 「色検」と記入		内装色 ()		乗車定員 4人		P3 P4 AW サンルーフ 革シート	
左・右 左・右		輸入 区分		ディーラー 並行		リサイクル料 8,960円・預託金		エアバック ABS ナビ TV キーレス	
セールスポイント キーレスエントリー/運転席エアバック/助手席エアバック								修復歴 有・無	
検査記入欄 エンジン回りオイル漏れ 外装小傷 室内汚れ、傷 シート汚れ ホイールカバー× スタッドレスタイヤ								A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥け G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換車 登録No. 月 日 までに名義できる方 車体 番号 RA1-241164 シリアル No.	
PW トビ石 傷A フレ 外装 A・U 小 ホイル A・曲 エアロ 内装 ヨコシ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ								長さ cm 幅 cm 高さ cm 最大積載量 Kg	