


2001 Toyota Verossa VR25		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GH-JZX110kai	DISPLACEMENT 2,491 cc		
YEAR / REG. 2001/07	MILEAGE 187,670 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Sedan		
CHASSIS NO. JZX110-6020574	DIMENSIONS (L X W X H) 471 × 176 × 145 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Front damage present, other modifications present. Front support distorted, right front inner panel has a processed hole, and left/right rear fender arches are processed. Vehicle is a color change. Aftermarket seat torn, aftermarket front bumper, cut processing. Interior scratches, dashboard lifting, body paint unevenness/lifting, underbody rust, and aftermarket steering wheel (airbag missing).			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H13/7月	メーカー トヨタ	ドア枚数 4	ボディ形状 セダン	評価点 3
車名 ヴェロッサ	グレード VR25	駆動区分 2WD 4WD		
車種 乗用車・その他 ()	排気量 2500 cc	型式 GH-JZX110kai	通称 A・B・C	
年 18	月 7	日 0	走行 187,670 km	
カラー グレー2	内装色 グレー	エンジン 2.5L 4缸 DOHC VZ	MT	
色替 ()	5人	新車登録のみ O印 を記入		
左・右 左・右	ディーラー ディーラー	走行 12,290 km	エアバック	ABS ナビ TV キーレス
セールスポイント 社外マフラー、社外ラジエーター、社外インタークーラー、5速マニュアル駆動公認、社外エアクリナー、社外アルミホイール、車高調、社外LSD、社外ステアリング、社外オーバーフェンダー				
特記事項 改造内容:動力伝達装置				
検査記入欄 F 損傷有り、他加工有り、F サポートヒズミ、右Fインパネ加工穴、左右Rフェンダーアーチ部加工、色替車、外品シート? 切れ、外品Fバンパー?、切断加工、ルーム内キズ、ダッシュ板ウキ、ボディPムラPウキ、下廻りサビ、社外ステアリング(エアB欠)				
				
修復歴 有 . C				
A キズ B ヘッドランプ C キズ・ヘッドランプ D 色あせ・ボケ E ガラスキズ W 軽傷 S サビ C 腐食 X 交換済 YX 交換済				
登録月 月 日 まで(に名実である方)				
車体番号 JZX110-6020574				
内装 シロ ヤブレ コブ コブ穴 オーディオA				
重量 全重 1,450 kg 最大積載量 450 kg				