


2002 Honda Integra 3HB 2.0 iS		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LA-DC5	1,998 cc		
YEAR / REG.	MILEAGE		
2002/11	126,000 km		
DOORS	SEATS		
3	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Coupe		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DC5-1011968	439 × 173 × 140 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Roof and bonnet repainted, steering wheel scuffed, interior dirty.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H14/11月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 3.5																				
車名 インテグラ	グレード 2.0 IS 5速マニュアル 社外アルミホイール	駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 2000 cc	型式 LA-DC5	通称 型式	内装 A・⑨・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送り品 (保証書・取扱説明書 等)																					
走行 126,000 km	シフト フロア 5 MT																							
外装色 シルバー II	カラーNo. ()	エアコン A・A・G・WAG・()	新着品のみ O印 を記入																					
内装色 ()	乗車定員 4 人	PS ⑨	AW ⑨	サンルーフ ⑨																				
ハンドル 左・()	輸入 区分	ディーラー ・ 並行	ナビ ⑨	TV ⑨																				
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/H I D・キセノン・ディスチャージ		11,310 円・ 預託金																						
検査記入欄 ルーフ ボネット色替え ハンドルすれ有 ルーム内汚れ																								
		修復歴 有・⑨																						
		<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>			A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
		登録No. 月 日 までに名変できる方																						
		車検番号 DC5-1011968																						
FW トビ石		備A	ワレ	外装 小 A・U A・曲 A・ワレ	エアロ No.	シリアル No.																		
内装 ヨゴレ	シミ	ヤブレ	コガ コガ穴	オーディオ穴	スレ	長さ cm	幅 cm	高さ cm	最大積重量 kg															