

2002 MAZDA Roadster 1.8VS		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
NB8C	1,839 cc		
YEAR / REG.	MILEAGE		
2002/01	135,480 km		
DOORS	SEATS		
2	2		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Convertible		
CHASSIS NO.	DIMENSIONS (L X W X H)		
NB8C-203853	396 × 168 × 124 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Leather)	
Bose Sound System			
INSPECTOR REPORT			
Dashboard small crack, side sill cover, broken stereo, interior trim scratches and fading, cracked steering wheel, exterior paint chips, door mirror minor damage, wheel minor damage, undercarriage minor rust/scratches, core support distorted, front instrument panel dent.			

初年度登録年月	車名	ドア	形状	グレード	評価点
14年1月	ロードスター	2	オープン	1.8 VS	3.5
国産車()	型式	GF-NBPC	排気量	1800cc	定員
				2人	
車検	14年1月→2月	フロア コラム ダッシュ	AT MTのみの記入 5速	エンジン・トランスミッション リアサスペンション ブレーキシステム ステアリング	外装 内装
走行 135480	MT: 無 車検時は併記を記入	冷却系 AC ガソリン・軽油		CS カウ パワ AW TV SR ナビ	B
外装色 白 内装色 黒	外装カラー No. 23C	輸入車 年・不明	D車・並 右・左H	純正品のみ丸印	
新車保証書	取扱説明書	R券 ¥	100900	名変期間	月 日迄
注意事項	備品目【 不具合箇所等 ケンウッドラジオ (SDR) ターボ オーディオセレクトリッド (併用) タイヤ本SS カリガススタッドレス S.S. 8分山	1	NBPC-203853		
検査員記入	ガラス④-X要ス フロント④-Coge穴・汚損・破れ				
9.6.10.12. 512.24	279.6.1.2.5.4				
9.6.10.12.14. 27.12.12.14	6.6.1.1.2.5.4				
内見り9.6.11.14. 11.6.12.14					
外観P.T.C. 14.6.12.14					
本館A. F. 14.7.5					

The diagram shows the front view of the car with labels for various parts:

- A: Headlights
- B: Bumper
- C: Grille
- D: Hood
- E: Engine compartment
- F: Front fender
- G: Wheel arch
- H: Wheel
- I: Tire
- J: Suspension
- K: Lower fender
- L: Side skirt
- M: Rear wheel arch
- N: Rear wheel
- O: Rear tire
- P: Rear suspension
- Q: Rear fender
- R: Trunk lid
- S: Rear window
- T: Spoiler