


2003 MAZDA Atenza Sport Wagon 2.3 23Z		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE UA-GY3W	DISPLACEMENT 2,260 cc		
YEAR / REG. 2003/11	MILEAGE 120,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. GY3W-118527	DIMENSIONS (L X W X H) 469 × 178 × 144 cm		
SALES POINTS			
Alloy Wheels Navigation System		Leather Seats (Leather, Suede-style Fab...	
INSPECTOR REPORT			
Seat sagging, stains, minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H15/11月	メーカー マツダ	ドア枚数 5	ボディ形状 ステーションワゴン	評価値 4
車名 アテンザスポーツワゴン	グレード 2.3 23Z 修復歴無	駆動区分 2WD	MT5速	
キーレス	HDDナビ	ETC	4WD	
車種 自家用・その他 ()	排気量 2300	型式 CC	UA-GY3W	内装 A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 120,000	キロ	マイル	フロア 5	MT
外装色 パールホワイト	カラーNo. (25D)	エアコン	ABS・AAG・WAG・()	装備品のみ O印 を記入
内装色 ()	乗車定員 5人	サンルーフ	革シート	
左・前 左・前	ディーラー・走行	リサイクル料	12,540円	預託金
セールスポイント キーレスエントリー/運転席エアバック/助手席エアバック/HDDナビ/ETC/HID・キセノン・ディスチャージ/CD/MD				
検査記入欄 シートへたり、シミ 外装小傷あり	修復歴 有・無			
	A	キズ	U	へこみ/サレ
	B	キズ/ヘコ	P	色あせ/サケ
	G	ガラスキズ	W	補修跡
	S	サビ	C	腐食
	X	交換部	XX	交換済
登録No.	名義中			
車体番号	GY3W-118527			
FW	トビ石	傷A	ワレ	外装
小	A・U	A・曲	A・フレ	エアロ
シリアル	No.			
内装	ヨゴレ	シミ	ヤブレ	コガ
コガ穴	オーディオ	CD	取組	長さ
最大積載量	Kg			