

2003 MITSUBISHI Pajero Io 5D ZR 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE H77W	DISPLACEMENT 1,999 cc		
YEAR / REG. 2003/12	MILEAGE 61,170 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE SUV		
CHASSIS NO. H77W-5401028	DIMENSIONS (L X W X H) 398 × 168 × 171 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Glass has minor scratches and needs repair. Interior has minor scratches, dirt, and tears. Stereo is missing, and there are significant scuffs. Wheels and door mirrors have minor scratches. The undercarriage's power steering component is scraped and damaged. The exterior has minor scratches, and the tail light is cracked.			

初年度登録年月		車名		ドア	形状	グレード	評価点
15年12月		パシフィカ 5W		2	ER	4WD	3.5
車庫 ()		型式 TA-H77W		排気量 2000cc		定員 5人	
車検 年 月 日				セールスガイダント		[外装] B	
走行 十 万 千 百 十 一				スロア MTのみ コラム 記入 ダツシュ 速		[内装] B	
61170				冷房 AAC ガソリン軽油		純正品のみ丸印	
外装色内装色				PS PS-W AW SR ガソリン 7000cc TV ナビ			
新車保証書 取扱説明書 R券 ¥12430				名変期限 月 日迄			
後日品 []				H77W-5401028			
注意事項 不具合箇所等							
検査員記入 ガラス ④ X 要ス 更内 ④ ④ の 汚カ 破れ							
ステアリング、ブレーキ							
左側 A、右側 A							
フロント、リア、サイド							
7-1076							
長さ cm		幅 cm		高さ cm		重量 kg	