

| 2003 MITSUBISHI Pajeromini VR                                                                                                                                                                                                                               |                                              | OVERALL  |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------|----------|
|                                                                                                                                                                                                                                                             |                                              | 3.5      |          |
|                                                                                                                                                                                                                                                             |                                              | EXTERIOR | INTERIOR |
|                                                                                                                                                                                                                                                             |                                              | -        | -        |
| MODEL CODE<br>H58A                                                                                                                                                                                                                                          | DISPLACEMENT<br>659 cc                       |          |          |
| YEAR / REG.<br>2003/09                                                                                                                                                                                                                                      | MILEAGE<br>70,715 km                         |          |          |
| DOORS<br>3                                                                                                                                                                                                                                                  | SEATS<br>4                                   |          |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                                                                                           | TRANSMISSION<br>AT                           |          |          |
| FUEL<br>Petrol                                                                                                                                                                                                                                              | STEERING<br>Right                            |          |          |
| EXTERIOR COLOR<br>Brown                                                                                                                                                                                                                                     | BODY TYPE<br>Kei                             |          |          |
| CHASSIS NO.<br>H58A-0500347                                                                                                                                                                                                                                 | DIMENSIONS (L X W X H)<br>340 × 148 × 164 cm |          |          |
| SALES POINTS                                                                                                                                                                                                                                                |                                              |          |          |
| Alloy Wheels                                                                                                                                                                                                                                                |                                              |          |          |
| INSPECTOR REPORT                                                                                                                                                                                                                                            |                                              |          |          |
| Steering wheel wear, dirty headliner, minor scratches/dents on wheels and door mirrors, exterior fading/peeling, undercarriage (power steering, battery surface corrosion/wear), oil seepage, core support distortion, minor dent on left instrument panel. |                                              |          |          |

ORIGINAL JAPANESE AUCTION SHEET

|                                                                                                       |                  |                            |            |               |            |
|-------------------------------------------------------------------------------------------------------|------------------|----------------------------|------------|---------------|------------|
| 初度登録年月<br>15年9月                                                                                       | 車名<br>パジェロミニ     | ドア<br>3W                   | 形状<br>VR   | グレード<br>4WD   | 評価点<br>3.5 |
| 型式<br>TA-H58A                                                                                         | 排気量<br>660 cc    | 定員<br>4人                   |            |               |            |
| 車検<br>6年9月11日                                                                                         | 走行<br>70710 km   | 燃料<br>ガソリン                 | エアコン<br>AC | セパレート<br>キ-VR | 外装<br>B    |
| 外装色<br>A-シ                                                                                            | 内装色<br>S/E       | 輸入<br>年・月                  | 車種<br>D車・並 | 右・左<br>右      | 内装<br>B    |
| 新車保証書<br>取得説明書                                                                                        | R券<br>¥1,007,000 | 名実期限<br>月                  | 日迄         | 純正銘のみ<br>気印   |            |
| 注意<br>事項                                                                                              | 検品品目<br>不具合箇所等   | H58A-0500347               |            |               |            |
| 検査員記入<br>ガラス④X要ス<br>シート④コゲ穴・破れ<br>ハンドル<br>天板リボ<br>ホィール・ドアミラー<br>外装7セ・11セ<br>下回りP.S.・パワーステアリング<br>オイル等 |                  | コゲ穴・破れ<br>右サイドミラー<br>小A・小U |            |               |            |

