

2003 Suzuki Jimny XC TB 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE JB23W	DISPLACEMENT 658 cc		
YEAR / REG. 2003/10	MILEAGE 80,420 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. JB23W-333786	DIMENSIONS (L X W X H) 340 × 148 × 172 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
INSPECTOR REPORT			
Glass A X needs repair, Seat A has burns, holes, and tears, Outer handle covers A/B missing (F/R unknown), Right front instrument panel warped, body cover damaged, Headliner dirty, rod end boot torn, Left and right rear fenders and steel panels corroded, Left and right steps have cut-out modification marks, drilled holes, A/B lamps not working, Front glass surround has rust, oil seepage, exterior paint peeling, door mirror lifting, Underbody frame has surface corrosion and paint peeling, repair marks, frame paint peeling, front/rear inner frame has surface corrosion holes.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 車名		ドア 形状 グレード		評価点
15年10月 ジムニー		3W XC A-ボ 4WD		R
車検月 () 型式 JA-JB23W		排気量 660cc 定員 4人		
車検 年月日	フロア AT	外装色 (リフトアップ)		[外装]
走行 80420 km	コラム MTのみ 5速	前後ラジアルロード		C
外装色 シルバー	ダッシュ	ABSシステム		[内装]
内装色	燃料 ガソリン 軽油 ()	ミラー 前後ドラレコ		B
新車保証書	取扱説明書 R券 ¥ 8,540	エンジンオイル		
注意事項	後日品	PS ()		
検査員記入	ガラス X要ス	AW ()		
ガラス X要ス	車内 X要ス	SR ()		
ガラス X要ス	車内 X要ス	TV ()		
ガラス X要ス	車内 X要ス	ナビ ()		
ガラス X要ス	車内 X要ス	純正品のみ		
ガラス X要ス	車内 X要ス	丸印		
ガラス X要ス	車内 X要ス	名義期限 月 日迄		
ガラス X要ス	車内 X要ス	JB23W-333786		
ガラス X要ス	車内 X要ス	図2		
ガラス X要ス	車内 X要ス	スベア		
ガラス X要ス	車内 X要ス	小A 小U		