

2004 Honda CR-V Fullmark iL-S		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-RD5	DISPLACEMENT 1,998 cc		
YEAR / REG. 2004/03	MILEAGE 168,611 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. RD5-1250115	DIMENSIONS (L X W X H) 436 × 178 × 171 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior has scratches, dents (P), peeling/cracks, rust. Headlights have scratches. Interior has scuffs, dirt, stains, scratches. Film is torn.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H16/3月	メーカー ホンダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 3.5
車名 C R - V	フルマーク i L - S	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 cc	型式 ABA-RD5	通称 形式	内装 A・B
車検 9年3月	抹消 燃料 ハイブリッド	ディーゼル シフト	検出過剰品 (保証書・取扱説明書 等)	
走行 168,611 km	インパネ	AT		
外装色 ホワイト	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 5人	PS	AW
左・右 左・右	ディーラー・並行	13,050円・預託金	エアバック	サンルーフ
セールスポイント ★ユーザー買い取り車！ETC！4WD！		修復歴 有・無		
検査記入欄 外装キズ凹みPハゲワレ錆、ヘッドライトキズ、内装スレ汚れシミキズ、フィルム破れ		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までに名実できる方 車体番号 RD5-1250115 FW トピ石 傷A フレ 外装 小 ホイール エアロ 内装 30シ ヤブレ コガ コガ穴 オーディオ穴		
		長さ cm 幅 cm 高さ cm 最大積重量 Kg		