


2004 Honda Integra 3HB Type S Third-Party Inspected 5MT/Navi/Full-Seg		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DC5	DISPLACEMENT 1,998 cc		
YEAR / REG. 2004/11	MILEAGE 87,251 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Coupe		
CHASSIS NO. DC5-2300837	DIMENSIONS (L X W X H) 439 × 173 × 140 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Third-party AIS inspection, rated 4.0. Driver's seat wear A, door trim A, steering wheel wear, minor console A, exterior touch-up paint marks, minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H16/11月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 4
車名 インテグラ	グレード タイプS・第三者機関査定済み・5速MT/ナビフルセグ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 CC	型式 DC5	通称 型式	内装 A・B・C
車検 9年11月	燃料 ガソリン	ディーゼル	検出過剰品 (保証書・取扱説明書 等)	
走行 87,251 km	シフト フロア 5 MT			
外装色 ビビッドブルーパール	カラーNo. B520P	エアコン AG・BG・WAG・ ()	装備品のみ O印 を記入	
()	内装色 黒	乗車定員 4人	PS	サンルーフ
ナビ 左・右	輸入区分 ディーラー・並行	リサイクル料 11,560円・預託制	エアバック	ABS
セールスポイント ★AIS 検査済み★5速MT★i-VTEC★メモリーナビ★フルセグ★HIDライト★momoステアリング★純正アルミホイール★前後ドラレコ★キーレスキー★電動格納ミラー				
検査記入欄 第三者機関【AIS 検査員意見参照】 AIS 評価点 4.0点 運転席すれ小 ドア内張りA ハンドルすれ コンソールA小 外装タッチアップ 外装仕様		修復歴 有・無 A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換車 XX 交換済 登録No. 月 日 までに名義できる方 車体番号 DC5-2300837 シリアル No. 長さ 幅 高さ 最大積重量 cm cm cm Kg		