

2004 SUBARU Legacy B4 3.0 R Spec B 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-BLE	DISPLACEMENT 2,999 cc		
YEAR / REG. 2004/12	MILEAGE 167,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. BLE-012124	DIMENSIONS (L X W X H) 464 × 173 × 144 cm		
SALES POINTS			
Alloy Wheels Navigation System		LEGACY Premium Sound System (140...	
INSPECTOR REPORT			
Seat wear, dashboard crack, minor underbody rust, right front instrument panel distortion, rear panel lower part has distortion, minor scratches and dents, steering wheel scuffs and scratches.			

ORIGINAL JAPANESE AUCTION SHEET

車種 H16 12月	メーカー スバル	ドア枚数 4	ボディ形状 セダン	評価点 R					
車名 レガシィ B 4	グレード 3.0 R スペック B 4WD 6速 マニュアル	駆動区分 2WD	年式 車検 R 9 年 2月11日						
車庫 自家用・その他 ()	排気量 3000 cc	型式 CBA-BLE	通称 型式	内装 A・B・C					
車検 9 年 2 月 / 抹消	燃料 ガソリン	ディーゼル	検日通り品 (保証書・取扱説明書等)						
走行 167,000 km	シフト フロア 6 MT								
外装色 オプシディアンブラックパール	カラーNo. ()	エアコン	新着品のみ O印 を記入						
乗車人数 ()	乗車定員 5 人	安全装置 ()	サンルーフ	高シート					
小まめ 左・右 部分	ディーラー 車行	13,590 円	エアロック	ナビ TV					
セールスポイント									
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/4WD/盗難防止システム/H I D ・キセノン・ディスチャージパワーシート/CD/MD									
検査記入欄									
シートへたり ダッシュ板ワレ 下廻りサビS 右フイ ンパネヒズミ Rパネル下部ヒズミ小キズ有へこみ有 ハンドルスレホイールキズ									
修復歴									
G . 無									
検査項目									
A	キズ	U	へこみ/サビ	B	キズ/へこみ	P	色あせ/汚れ	Q	ガラス/キズ
W	燃費	S	サビ	C	腐食	X	交換済	XX	交換済
売却No.					名義中				
月					日				
車体番号					BLE-012124				
FW	トボ石	傷A	フレ	外装	小	ホイール	エアロ	シリアル	
内装	ゴケ	シミ	ヤブレ	コゲ	コガ穴	オーディオ穴	スレ	長さ	幅
					高さ	最大積載量	kg		