

2004 Volkswagen VW Polo 5HB EU		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 9NBBY	DISPLACEMENT 1,389 cc		
YEAR / REG. 2004/05	MILEAGE 31,090 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Left		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. WVWZZZ9NZ4U021429	DIMENSIONS (L X W X H) 389 × 167 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Glass needs repair/replacement. Seats have burns, holes, and tears. Steering wheel scuffs, headliner cracks and stains. Engine panel distortion. Dashboard lifting, stickiness, mold, and stains. Interior trim cracks and peeling, meter area scratches and stains. Oil seepage. Wheels condition A. Antenna damaged/missing. Exterior paint rust.			

初年度登録年月	車名	ドア	形状	グレード	評価点
16年5月	アルファード・ガンボロ5H8			FU左ハンドル	3.5
車種	型式	排気量	定員		
乗用車	GH-9NBBY	1400cc	5人		
車検 A8年4月14日					
走行	フロア コラム ダッシュ	AT MTのみ 速	左ハンドル パナソニックETC		
外装色	内装色	エンジンオイル	外装		
シルバー	AC	ガソリン	B		
外装色	内装色	エンジンオイル	B		
新車保証書	取扱説明書	R券	円迄		
後日品【 不具合箇所等 バックカメラ タイヤバルブレンチ等8カ所】	注意事項				
検査員記入	ガラス④X要ス 窓①②コゲ・穴・汚破れ				
11/10/20 天候リフレ・雨降	工場不良品計				
分組別検査、バグ等、対応済み					
内視鏡検査、1-2-通品11/10/20					
オレインジ、オレイン					
7-10-X、作業完了					
長さ	幅	高さ	積載重量	kg	
cm	cm	cm	kg		