

2005 BMW BMW 1series 116i Official Dealer Car Xenon Navigation		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GH-UF16	DISPLACEMENT 1,596 cc		
YEAR / REG. 2005/12	MILEAGE 38,400 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. WBAUF12070PN29064	DIMENSIONS (L X W X H) 424 × 175 × 143 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Right rear fender dent, front bumper damage.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H17 / 12月		メーカー BMW		ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 1シリーズ		グレード 116i 正規ディーラー車		駆動方式 4WD																						
車種 乗用車	その他 ()	排気量 1600 cc	型式 GH-UF16	燃料 ガソリン	ディーゼル	内装 A・⑤・C																				
年 38	月 4	日 00	走行 38,400 km	検日選り品 (保証書・取扱説明書 等)																						
シルバー		カラーNo. ()	エアコン AC・A/C・WAG・()	整備品のみ ○印 を記入																						
()		内装色 ()	乗車定員 5 人	サンルーフ 本革シート																						
左・⑤	右・⑤	デュー	並行	16,940 円	エア/サグ	TV																				
セールスポイント CD/HID (キセノンライト) /エアバック/バックモニター 社外ナビ・DVD再生				修復歴 有・⑤																						
検査記入欄 右Rフェンダー凹み Fバンパー傷				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あは・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>軽傷跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換要</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコミ/サレ	B	キズ・ヘコミ	P	色あは・ボケ	G	ガラスキズ	W	軽傷跡	S	サビ	C	腐食	X	交換要	XX	交換済
A	キズ	U	ヘコミ/サレ	B	キズ・ヘコミ	P	色あは・ボケ	G	ガラスキズ																	
W	軽傷跡	S	サビ	C	腐食	X	交換要	XX	交換済																	
登録No.				名義中																						
月				日																						
車体番号 WBAUF12070PN29064																										
FW	トビ石	傷A	ワレ	外装	⑤・U	ホイール																				
内装	⑤・U	⑤・U	⑤・U	⑤・U	⑤・U	⑤・U																				
長さ	424 cm	幅	175 cm	高さ	143 cm	最大積載量																				