


2005 SUBARU Legacy B4 3.0 R Spec B 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-BLE	DISPLACEMENT 2,999 cc		
YEAR / REG. 2005/03	MILEAGE 239,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Sedan		
CHASSIS NO. BLE-0127707	DIMENSIONS (L X W X H) 464 × 173 × 144 cm		
SALES POINTS			
Alloy Wheels		LEGACY Premium Sound System (140...	
INSPECTOR REPORT			
Right front instrument panel bent, dashboard cracked, interior has tears and dirt, seats are sagging and scuffed, and there are minor scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H17/3月	メーカー スバル	ドア枚数 4	ボディ形状 セダン	評価点 R
車名 レガシィ B 4	グレード 3.0 R スペック B 4WD 6速マ ニュアル タイミング チェーン式エン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 3000 cc	型式 CBA-BLE	通称 型式	内装 A・B
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検出過剰品 (保証書・取扱説明書 等)	
走行 239,000 km	シフト フロア 6 MT			
外装色 アーバングレー・メタリック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 5 人	PS	サンルーフ
左・右 左・右	ディーラー ディーラー	走行 13,490円	エアロック	ナビ
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エ アバック/4WD/盗難防止システム/H I D ・キセノン・ ディスチャージパワーシート/C D /MD				
検査記入欄 右フインパネ曲がり ダッシュ板ワレ キレ ルーム内 汚れ シートへたリスレ 小キズ有へこみ有		修復歴 0 . 無		
		A キズ U ヘコみサレ B キズヘコミ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換車 XX 交換所		
		登録No. 月 日 までにも名変更できる方		
		車体 番号 BLE-0127707		
		シリアル No.		
FW トピ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	長さ 幅 高さ 最大積載量 cm cm cm Kg			
内装 ヨゴレ シス ヤブレ コゲ コゲ穴 オーディオ穴 スレ				