

2005 SUBARU Legacy TouringWagon 2.0 GT-II 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE TA-BP5	DISPLACEMENT 1,994 cc		
YEAR / REG. 2005/06	MILEAGE 81,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. BP5-083996	DIMENSIONS (L X W X H) 468 × 173 × 147 cm		
SALES POINTS			
Alloy Wheels Navigation System		LEGACY Premium Sound System (140...	
INSPECTOR REPORT			
Dash panel crack, alloy wheel scratches, interior dirt, rear panel B-grade damage, windshield crack, door mirror A-grade damage, minor scratches and dents, severe underbody rust.			

出 品 票		型式認定番号		商標登録番号		シリアル番号		評価点	
年度登録 H17 4月 日		車 名		AT数		グレード		年制 型式 年制	
H17 4月 日		レガシィツーリングワゴン				2.0GT-II		9	
型式		BP5		排気量		2000 cc		燃料 油圧	
車種		技術済み		家庭用/商用車		シャフト		純正部品 AT	
車型		車型		車種		AT		純正部品 AC	
走行距離		8万0千575 km		マイル (交換)		(改定)		純正ナビ ナビ	
外装色		グレー		色替(白)		色替黒		ツヤ輝類(社外品含む)	
車台No.		BP5		083996				フルセグ ワンセグ デナビロ	
登録No.				リサイクル 標法		13,560		ナビ輝類(社外品含む)	
定員		5人		乗客量		満員		HBD DVD SD	
輸入車のみの 型式		年		輸入区分		ディーラー		後日取込品	
セービスポイント				車台		ハンドル		後日取込品	
社外		アルミホイール4WD車ターボ車		ETC		ABS走行距離		80575 KM	

注意事項・不具合箇所

検査員記入欄：新設「有」の場合は新設箇所・交換箇所を記入
 ダッシュ板ワレ
 廉キズ
 ルーム内汚れ
 RパネルB
 W/C ADミラーA
 小キズ有へこみ有
 下廻りサビS

Fミラー キズ ヒビ フレ