

2005 MITSUBISHI Pajero 3D ZR 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE V63W	DISPLACEMENT 2,972 cc		
YEAR / REG. 2005/10	MILEAGE 101,120 km		
DOORS 3	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. V63W-0500391	DIMENSIONS (L X W X H) 426 × 190 × 185 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Glass damage. Interior has minor damage, burn marks, holes, and tears. Steering wheel is worn. Headliner is dirty. 4WD indicator lamp is not working. Minor damage to outer wheels. Headlight coating is peeling. Oil seepage. Rear spoiler paint damage and undercarriage rust/paint damage.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初度登録年月	車名	ドア	形状	グレード	評価点	
	17年10月	パジェロ	3W	ZR	4WD	4	
車検	車検月	型式	排気量	定員			
	10/1	LA-V63W	3000cc	5人			
走行	年	月	日	フロア	AT	マッドガード16インチETC	
10/1/20				コラム		コンベヤハンドル	
ダッシュ				MTのみ記入			
外装色	黒	内装色		冷房	AAC		
外装カラーNo.	X24	輸入車	年・不明	D車・並	右H・左H		
新車保証書	取扱説明書	R券	¥11,130	名変期限	月	日迄	
注意	後日品	不具合箇所等	ストラ・ダビ・フルセグTV	車検No.	V63W-0500391		
検査員記入	ガラス	④・X要ス	④コゲ・穴・④破れ				
ハンドル	④天板	④汚れ					
4WDランプ	④点検						
外装	④点検						
ヘッドライト	④点検						
オイル	④点検						
Rスポン	④点検						
Fスポン	④点検						
長さ	cm	幅	cm	高さ	cm	重量	kg