

2005 Nissan Bluebird Sylphy 2.0 20M		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-KG11	DISPLACEMENT 1,997 cc		
YEAR / REG. 2005/12	MILEAGE 37,300 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Sedan		
CHASSIS NO. KG11-006113	DIMENSIONS (L X W X H) 461 × 170 × 151 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
AIS Inspection: Rated 3.5 stars. Minor scuffs/scratches on mirrors, seats, door trim, steering wheel, and console. Exterior shows color fading and minor scratches. Front bumper bottom damaged, rear bumper bottom has minor scratches. Headlights are cloudy.			

印字位置確認 H17 / 12 月		日産 車名 ブルーバードシルフィ		ドア数 4 ボディカラー セダン		評価点 3.5	
車種 自家用・その他 ()		年式 2000 CC		型式 DBA-KG11		内装 A・B・C	
車検 - 年 - 月 - 日		燃料 ガソリン		ディーゼル ()		貴重品等品目 (保証書・取扱説明書等)	
走行 37,300 km		シフト フロア CVT		車検 年 月 日			
外装色 カラークラッシュ (QX1)		エンジン QD・AAG・WAD・()		装備品のみ O印 を記入			
白ワイドパール3コートパール (QX1)		車検 5 人		(P) (P) (A) サルファー 革シート			
()		内装色		(P) (P) (A) サルファー TV			
左・(要) 輸入 走行 12,380 円		フライウトル制		エアコン			
セールスポイント							
インテキー純正ナビフルセグTV/バックカメラE.TC/純正アルミノアエオエアン							
検査記入欄							
< < AIS 検査 > > AIS 評価 3.5 点 ☆ミラーA/シートすれ < 小 > ドア内張りA < 小 > ハンドル擦れ < 小 > コンソールA < 小 > 外装色擦れ・外装小傷有・F/バン下面有・R/バン下面A有り・ヘッドライトくもり							
修復歴 有 ()							
車検 年 月 日							
車検番号 KG11-006113							
車検 年 月 日							