

2005 R1 660 R		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-RJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2005/04	MILEAGE 197,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. RJ1-	DIMENSIONS (L X W X H) 329 × 148 × 151 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Front bumper bottom A, minor scratches around wheels, aftermarket pillar, interior trim scratches, light interior dirt. Door trim scratches, seat scratches/scuffs, minor console damage. Exterior light line scratches, door mirror paint peeling. Power window switch faulty, rear wiper missing.			

初年度登録		メーカー		トク後数		ボディ形状		評価点	
H17 / 4月		スバル		3		コンパクトハッチバック		9.5	
		車名		グレード		駆動方式			
		R 1		660 R タイミングベルト交換済みステッカー有		2WD 4WD			
車種		自家用 ・ その他 ()		排気量		型式		内装	
		660 CC		CBA-RJ 1		運転形式		A・B・C	
車検		- - - 年 / - 月 / - 日		燃料		ディーゼル		償目通り品 (保証書・取扱説明書等)	
		EIA		ハイブリッド ()					
走行		口内にマークを記入(金・交換・事故・盗難・火災) 名称車検印(円) 内装色()		シフト					
		1万9千000マイル		インパネ CVT					
外装色		カラー-No.		エアコン					
チタニウムグレー・メタリック		()		Q&D・AAD・WAG・()					
()		内装色		標準定員		4人			
ハンドル		左・右		輸入国		ディラー		走行	
		9,330円		リサイクル料		エレクトロニック		ナビ	
セールスポイント									
キーレスエントリー/A B S / 運転席エアバック/助手席エアバック/D									
Fバンパー下面A小足廻り社外ビラー内強傷中室内落汚れ ドア内強傷中シートすれ有コンソール庫小 外装うすい線キズドアミラーP割れ PWスイッチ不良リヤワイバ部品									
検査記入欄									
A	キズ	U	ヘコみ凹痕	B	キズへこみ	P	色あせ・汚れ	G	ガラスキズ
W	修理跡	S	サビ	C	腐食	X	交換機	XX	交換所
登録地									
RJ 1-									
車体番号									
FW トボ石 備A フレ 外装 小 A・U A・曲 A・ウレ エプロ シリアル No.									
内装 エゴレ ショ ヤブレ コガ コグス オークチャス スレ 革調									
備 備 備 備 備 備 備 備 備 備									