

2005 Subaru Forester 2.0X		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-SG5	DISPLACEMENT 1,994 cc		
YEAR / REG. 2005/04	MILEAGE 246,242 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE SUV		
CHASSIS NO. SG5-090602	DIMENSIONS (L X W X H) 449 × 174 × 159 cm		
SALES POINTS			
Roof Rails		Navigation System	
INSPECTOR REPORT			
Engine oil leakMinor exterior scratchesInterior has odor and dirtSeats have large stains, medium scuffs, and wearCarpet has cuts and large tearsSteering wheel scuffsInterior trim scratches			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H17/4月	メーカー スバル	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 3
車名 フォレスター	グレード 2.0X	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 CC	型式 CBA-SG5	通称 4WD	内装 A・B
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検定通り品 (保証書・取扱説明書 等)	
走行 246,242 km	シフト フロア	AT		
外装色 シルバー	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 5 人	PS	サンルーフ
ハンド 左・右	輸入 区分	リサイクル料 12,710円	エアバック	ナビ
セールスポイント		AW TV キーレス		
検査記入欄		修復歴 有・無		
エンジン廻りオイル漏れ 外装うすい傷キズ 室内臭い、汚れ シートしみあ、すれ中、へたり カーペット汚れ、破れ大 ハンドルすれ 室内内装磨		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換車 YX 交換車 登録No. 月 日 までにも名実できる方 車体 番号 SG5-090602 シリアル No. 長さ 幅 高さ 最大積重量 cm cm cm Kg		
FW トビ	フレ	外装	小	ホイル
内装	ゴ	コ	コ	オー