

2005 Suzuki Twin Gasoline V		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE EC22S		DISPLACEMENT 658 cc	
YEAR / REG. 2005/08		MILEAGE 53,343 km	
DOORS 2		SEATS 2	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Black		BODY TYPE Kei	
CHASSIS NO. EC22S-220998		DIMENSIONS (L X W X H) 274 × 148 × 145 cm	
INSPECTOR REPORT			
Right front inside panel partially damaged. Exterior fully repainted (including color change), with a wavy radiator core support. Other trim shows partial damage, wrinkles, scuffs, and scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H17/8月		メーカー スズキ		ドア枚数 2		ボディ形状 軽四		評価点 4.5	
車名 ツイン		グレード ガソリンV		駆動区分 2WD 4WD					
車歴 自家用・その他()		排気量 660 CC		型式 EC22S		通称 型式		内装 A・B・C	
車検 -年-月/日		燃料 ガソリン		ディーゼル		後日送り品 (色紙書・取説等)			
走行 53,343 km		シフト ハイブリッド		フロア 3 AT					
外装色 マットブラック		カラーNo. ()		エアコン A・B・AAG・WAG・()		新備品のみ O印 を記入			
()		内装色 色紙書は()内に「色紙」と記入		乗車定員 2人		P P AW		サンルーフ 革シート	
ハンド 左・右		輸入 区分		ディーラー 並行		リサイクル料 7,510円・預託無		エディック ABS ナビ TV	
セールスポイント ワンオーナー/バックカメラ/運転席エアバック/キーレス エントリー/ABS/衝突安全ボディ									
検査記入欄 右フロントインサイドパネル損傷部分的 外装全塗装(色変え含む)波ありラジエータコアサポート 損傷 他トリムしわすれきず部分的									
修復歴 有 ()									
A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥き G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換車									
登録No. 月 日 まで(に)名義できる方									
車体 番号 EC22S-220998									
シリアル No.									
PW () 備A フレ 外装 小 A・U ホイル A・曲 エアロ 内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ									
長さ cm 幅 cm 高さ cm 最大積載量 Kg									