

2006 Daihatsu Copen Active Top		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
L880K	659 cc		
YEAR / REG.	MILEAGE		
2006/07	101,460 km		
DOORS	SEATS		
2	2		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Convertible		
CHASSIS NO.	DIMENSIONS (L X W X H)		
L880K-0033849	340 × 148 × 125 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Glass needs repair (X), with scratches, burns, holes, stains, and cracks. Exterior handle peeling. Dash has modification holes and an aftermarket navigation base. Front grille has scratches; meter area has scratches and stains. Non-standard wheels. Exterior PP peeling, undercarriage rust. Hood, front grille, and front bumper show color differences. EVC and other modifications present. Front side member and front bumper reinforcement are distorted.			

[illegible]